

Inspection Photos
Operator: Simcoe
API: 067-07379
Date: 3/2/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing largely with western wheatgrass, crested wheatgrass, and smooth brome.



Photo 3. View of the southern project area from the southeastern corner facing westward. Per communication with onsite contractors, excavation work is being conducted by the US Bureau of Reclamation to dredge and maintain irrigation canal that runs adjacent to the southern project area.



Photo 3. View of kochia debris, up to 4-ft tall observed on the well pad and in the southern project area (inset).



Photo 4. View of reference area comprised of open grass field with smooth brome, crested wheatgrass, and western wheatgrass observed.