

Interim Reclamation and Stormwater Inspection

March 7, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335539

Location Name: McPherson A Pad

Inspection Document #: 702800004

Garfield County, CO

NENW Section 16 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: McPherson A Pad
Facility #: 335539



Photo 1. Photo taken from the northwest corner of the Location facing southeast shows an overview of the Location.



Inspection Photos
Location Name: McPherson A Pad
Facility #: 335539



Photo 2. Photo taken from the northwest corner of the Location facing east shows areas of interim reclamation. A follow up inspection is necessary to properly assess interim reclamation when snow is not obscuring areas and vegetation is not dormant.



Photo 3. Photo taken from the southeast corner of the Location facing southeast shows areas of interim reclamation. See additional comments under Photo 2.



Inspection Photos
Location Name: McPherson A Pad
Facility #: 335539



Photo 4. Photo taken of subsidence occurring at dry and abandoned well that has been filled.



Photo 5. Photo taken at the northwest corner of the Location facing east where sediment from the dry and abandoned well appears to have been dumped on the pad, covering the gravel.



Inspection Photos
Location Name: McPherson A Pad
Facility #: 335539



Photo 6. Photo taken from the south corner of the Location facing west shows cut slopes covered in snow. A follow up inspection is necessary to properly asses stormwater management.



Photo 7. Photo taken from the southwest corner of the Location facing west shows erosion occurring on unprotected slopes.



Inspection Photos
Location Name: McPherson A Pad
Facility #: 335539



Photo 10. Photo taken from the northeast of the Location facing north showing an unstabilized berm.



Inspection Photos
Location Name: McPherson A Pad
Facility #: 335539



Photo 8. Photo taken from the north at the Location entrance facing south shows rills formed by water flowing through the Location.

Photo 9. Photo taken from the north at the Location entrance facing north shows sediment laden runoff leaving the location.

Inspection Photos
Location Name: McPherson A Pad
Facility #: 335539



Photo 10. Photo taken from the access road directly north of the Location entrance facing west showing where runoff is cutting into a berm adjacent to a culvert.



Inspection Photos
Location Name: McPherson A Pad
Facility #: 335539



Photo 11. Photo taken from north of the Location facing North. Photo shows an overview of the tie in point on a flowline (# 466720) with potentially impacted fluids accumulating around the tie in point. Note the arrow showing where potentially impacted fluids are flowing around the secondary containment berm and offsite with stormwater runoff.



Inspection Photos
Location Name: McPherson A Pad
Facility #: 335539



Photo 12. Photo taken from north of the Location facing south. Photo shows the tie in point on a flowline (# 466720) where potentially impacted fluids are flowing around the secondary containment berm and offsite with stormwater runoff.



Inspection Photos
Location Name: McPherson A Pad
Facility #: 335539



Photo 12. Photo taken from north of the Location shows potentially impacted fluids flowing offsite with stormwater and through the adjacent property.

