

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2022

Submitted Date:

03/09/2022

Document Number:

701600868

FIELD INSPECTION FORMLoc ID 312250 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

6 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Young, Rob		rob.young@state.co.us	
Lindley, Trent		trent.lindley@state.co.us	
Whittington, Ellice		ellice.whittington@state.co.us	
Dizghinjili, Victoria		vdizghinjili@kpk.com	All inspections
MacLaren, Joe		joe.maclaren@state.co.us	
Quint, Craig		craig.quint@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219870	WELL	PR	11/01/2019	OW	075-07533	KNUDSEN 7	PR

General Comment:

Routine FIR - Follow-up FIR for Doc#699602115, 699600431, 699601427 & 699601657. CA's cited in this FIR are revised with current CA dates, follow-up FIR will be performed for compliance verification following CA date cited within this FIR. See attached photographs for current conditions and CA's required.

Location			
Lease Road:			
Type	Access		
comment:	Maintain lease road, fill ruts between battery and PR well.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Satisfactory		Date:
Corrective Action:			Date:
Good Housekeeping:			
Type	DEBRIS		
Comment:	Remove all abandoned electrical equipment located at sites of abandoned transfer pump on west side of battery/facility, west of current transfer pump shack. See attached photographs #2, 3, 4 & 5.		
Corrective Action:	Comply with Rule 606		Date: 03/23/2022
Type	OTHER		
Comment:	Remove all flow lines at abandoned transfer pump sites and valve vault located west of CO battery and current transfer pump shed. See attached photographs # 2,3,4,5 & 6. Contact COGCC Flow-line Mechanical Integrity Group for directives		
Corrective Action:	Comply with Rule 1105		Date: 04/06/2022
Type	DEBRIS		
Comment:	Remove all concrete from location remaining from debris pile adjacent to PW tank/pit. Remove all concrete from sites of abandoned transfer pump pads located on west side of battery/facility. See attached photographs #1, 2, 3, 4 & 5.		
Corrective Action:	Comply with Rule 606		Date: 03/23/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil	Flow Line		
Comment:	Remove from location and appropriately dispose of stained/saturated soils within current transfer pump shed feeding CO tanks at battery. See photographs. Contact COGCC Environmental Group for directives.		
Corrective Action:	Comply with Rule 906		Date: 03/11/2022
Crude Oil	Flow Line		
Comment:	Appropriately remove from location all stained/saturated soils within current transfer pump shed feeding CO tanks at battery. See attached photographs. Contact COGCC Environmental Group for directives.		
Corrective Action:	Comply with Rule 905.e.		Date: 03/24/2022
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:	Livestock wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 0		
Comment:	No change in equipment or configuration inventoried		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	219870	Type:	WELL	API Number:	075-07533	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	See CA's listed within this FIR and comply with related Rule cited at facility/battery location.								
Corrective Action:						Date:			

Environmental**Spills/Releases:**

Type of Spill: NON E&P WASTE

Estimated Spill Volume: _____

Comment: Stained/Saturated soils within current transfer pump shed, properly remove all affected soils from location. Contact COGCC Environmental Group for directives.Corrective Action: Comply with Rule 906

Date: 03/11/2022

Reportable: NO

GPS: Lat _____

Long _____

Proximity to Surface Water:

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Use BMP's for erosion management](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701600869	Knudsen #7	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5687822