

Interim Reclamation and Stormwater Inspection

March 7, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 311643

Location Name: Valley Farms B

Inspection Document #: 702800006

Garfield County, CO

SENE Section 16 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Valley Farms B
Facility #: 311643



Photo 1. Photo taken from the southwest entrance to the location facing north shows an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800006

Inspection Photos
Location Name: Valley Farms B
Facility #: 311643



Photo 2. Photo taken from the north of the Location facing northeast shows interim reclamation areas. Presently, it appears that interim reclamation areas are dominated by bare ground and weeds (kochia and cheatgrass) and are not progressing towards reclamation standards.



Inspection Photos
Location Name: Valley Farms B
Facility #: 311643



Photo 3. Photo taken at the north of the location facing west shows unstabilized slopes not progressing towards reclamation standards. See additional comments under photo 2.



Inspection Photos
Location Name: Valley Farms B
Facility #: 311643



Photo 4. Photo taken at the southwest corner of the pad facing west shows slopes covered in snow. A follow up inspection is necessary to properly asses stormwater management. Exposed slopes show signs of rill erosion.



Inspection Photos
Location Name: Valley Farms B
Facility #: 311643



Photo 5. Photo taken at the southwest corner of the pad facing west shows rill erosion occurring on unstabilized slopes of the sediment trap.



Inspection Photos
Location Name: Valley Farms B
Facility #: 311643



Photo 6. Photo taken at the wells facing northeast shows wells completely inundated with stormwater.



Inspection Photos
Location Name: Valley Farms B
Facility #: 311643



Photo 7. Photo taken at the wells facing north shows well API # 05-045-12060. The arrow points to gas bubbling up in the water indicative of a potential leak.



Inspection Photos
Location Name: Valley Farms B
Facility #: 311643



Photo 8. Photo taken at the south of the Location facing southwest shows an anchor marker in disrepair. 3 of 7 counted anchor markers were in disrepair.