

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2022

Submitted Date:

03/09/2022

Document Number:

699602851**FIELD INSPECTION FORM**Loc ID 323450 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections
,		dnr_cogccengineering@state. co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245251	WELL	SI	03/01/2017	GW	123-13046	ROTH 12-30	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / CEMENTING** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations / Cementing. Final plugs, cement to surface.

Battery: Inactive | Shut-down.

Inactive Battery SE corner GPS coordinates: 40.455144 / -104.600555

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Jobsite safety signage present.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 245251 Type: WELL API Number: 123-13046 Status: SI Insp. Status: PA**Cement**Cement ContractorContractor Name: Axis Energy

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 2400'-307'-0'Cement Volume (sx): 215 sxsGood Return During Job: YESCement Type: Class "G" 15.8#Comment:

Workover Contractor: Axis Energy Services. Rig #714.

Cementing Contractor: Axis Energy Services.

Reference:

Form 6N on file. Notice of Intent to Abandon date: 01/26/2022. Approved.

Form 42 on file. Notice of MIRU.

Start Date: 03/01/2022. Approved.

Form 42 on file. Notice of Plugging Operations.

Start Date: 03/01/2022. Approved.

Form 17 Bradenhead Test on file. Date: 03/03/2022. Approved.

Final plugs. Cement to surface.

IWP: 0 PSI /0 PSI

HELD PJSM. CHECKED PSI. RU WL, RIH W/ PERF GUNS AND SHOOT HOLES@ 2,500', SHOOT 2ND HOLES@ 2.000', SET CICR@ 2,400', RD WL RIH W/ STINGER ON WS AND STING INTO CICR @2,400'. RU CEMENTERS, PUMP 10 BBLS MUD FLUSH, 5 BBLS FW, 190 SX OF CLASS G 15.8 PPG, 1.15 YLD CMT AND DUMP LAST 35 SX ON TOP OF CICR. PU TO BOS AND REV CIRC W/26 JTS. PU TO 307', 10 JTS TBG IN HOLE AND CHECK FOR BUBBLES. PUMP 25 SX OF CLASS G 15.8 PPG, 1.15 YLD CMT TO SURFACE. POOH AND LD TBG. ND BOP, NU WH.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 03/07/2022 at approximately 12:33 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: ROTH-66N64W /30NWSW Location ID: 323450 Well Name(s): Roth 12-30. API: 05-123-13046. Location County: Weld County, Colorado Weather: Mostly Sunny, wet w/ mud from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations / Cementing. Final plugs, cement to surface. Battery: Inactive Shut-down. Inactive Battery SE corner GPS coordinates: 40.455144 / -104.600555</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/09/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602853	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5688182