

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/02/2022

Submitted Date:

03/03/2022

Document Number:

689501335

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Brown, Kari On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Gorka, Ray		RGorka@kpk.com	<a href="#">KPK environmental</a>
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
Rickard, Jeff		JRickard@kpk.com	<a href="#">KPK environmental</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481685	SPILL OR RELEASE	AC			-	Musick-McClintock #5	EI

**General Comment:**

This is an environmental inspection of Spill ID 481685 (AC). Any corrective actions from previous inspections that have not been addressed are still applicable.

Photos attached to document site conditions.

**Inspected Facilities**

Facility ID: 481685 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: At the time of inspection crews were on site to excavate soil impacts; no excavation was currently in progress as crews were waiting on the return of trucks to haul waste off of location. The excavation was open and the flowline exposed. Soil impacts remained visible in-situ.

Corrective Action: Comply with COAs on Form 19 Doc No. 402968323. The Supplemental Form 19 for this spill is due 3/9/2022. Date: 03/09/2022

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Piles	Adequate		
Comment		Soils being stored on site were placed on a plastic liner and marked as 'contaminated'.		
Corrective Action				Date: _____

**Spill/Remediation:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402972967	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5681174">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5681174</a>
689501336	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5681156">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5681156</a>