

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/03/2022

Submitted Date:

03/03/2022

Document Number:

699804228

FIELD INSPECTION FORM

Loc ID: 334086 Inspector Name: De Paolo, Corey On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

General Comment:

COGCC Inspection Report Summary
On Wednesday 3/2/22 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted a storm water inspection at CAERUS PICEANCE LLC MURRAY-68S96W /1SESW, Location #334086 in Garfield County Colorado. While there, I spoke to Adam Roll he stated that a street sweeper would be arriving later that day. During this inspection the following compliance issues were observed:

1) Location lacks stabilization. Insufficient tracking BMP at entrance to location. Sediment has been transported on to County road 306 for approximately 100 yards.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
		Berms				
Ditches						
Gravel	Fail					Gravel insufficient
Other	Fail					Location lacks stabilization.
		Gravel				
				Vehicle Tracking	Fail	Sediment has been transported on to County
Berms						
		Sediment Traps				
		Ditches				
		Culverts				
Compaction	Fail					Insufficient tracking BMP at entrance to location
Sediment Traps						

Comment: Location lacks stabilization. Insufficient tracking BMP at entrance to location. Sediment has been transported on to County road 306 for approximately 100 yards.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 03/04/2022

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Storm water for corrective actions.	depaoloc	03/03/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402972212	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5680557
699804229	Photos for Insp. #699804228	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5680555