

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2022

Submitted Date:

03/03/2022

Document Number:

700703940

FIELD INSPECTION FORM

Loc ID 334833	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				Findings: 18 Number of Comments 6 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211148	WELL	PR	07/20/1997	GW	045-06907	DUNN 9-2	PR
260025	WELL	PR	02/01/2008	GW	045-07805	HILL 9-1 (B9)	PR
260065	WELL	PR	10/01/2020	GW	045-07814	DUNN 9-7 (B9)	PR
260066	WELL	PR	06/04/2002	GW	045-07813	HILL 9-8 (B9)	PR
274078	WELL	TA	06/08/2021	GW	045-13329	DUNN 9-1C (B9E)	TA
274079	WELL	PR	04/01/2013	GW	045-13330	DUNN 9-2C (B9E)	PR

General Comment: COGCC Inspection Report Summary On Wednesday 3/2/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus B9E, at Location # 334833 in Garfield county Colorado. Any Corrective Actions from previous Inspections that have not been addressed are still applicable. While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls. During this inspection the following compliance issues were observed: 1. Lack of battery signage. 2. Lack of stabilization in areas of access road and location. 3. Staining 4. One bird protector is not installed. 5. Valve on tank missing plugs/caps. 6. Open ended piping for thawing out dump lines on tanks with exhaust from trucks. Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:	See stormwater			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	Lack of battery signage.			
Corrective Action:	Provide proper signage			Date: 05/20/2022
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	OTHER			
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Staining			
Corrective Action:	Remove stained material			Date: 04/15/2022
Type	OTHER			
Comment:	Valve on tank missing plugs/caps.			
Corrective Action:	Eliminate possibility of wildlife to enter open lines for thawing out dump lines with exhaust from trucks.			Date: 03/18/2022
Type	OTHER			
Comment:	One bird protector is not installed.			
Corrective Action:	Install bird protector on separator burner.			Date: 03/18/2022
Type	OTHER			
Comment:	Valve on tank missing cap/plug			
Corrective Action:	Install cap/bull plug			Date: 04/08/2022
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

6

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: Portable rig heater

Corrective Action:

Date:

Type: Bradenhead

6

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

6

Comment:

Corrective Action:

Date:

Type: Bird Protectors

2

Comment: One is missing see housekeeping

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Compaction	Fail			

Comment: 1. Lack of stabilization in areas of access road and location.Corrective Action: Install or repair required BMPsDate: 04/15/2022**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402972757	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5680970
700703947	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5680962