

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2022

Submitted Date:

03/03/2022

Document Number:

700703941**FIELD INSPECTION FORM**Loc ID 334855 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211282	WELL	SI	12/01/2021	GW	045-07041	DUNN 4-16	SI
267800	WELL	PR	08/01/2019	GW	045-09216	DUNN 4-16B (P4E)	PR
267802	WELL	SI	12/01/2021	GW	045-09214	HILL 10-4B(R4E)	SI
272467	WELL	PR	09/18/2004	GW	045-10086	DUNN 3-13B (P4E)	PR
272469	WELL	PR	09/12/2004	GW	045-10087	DUNN 3-13C (P4E)	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 3/2/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus P4E, at Location # 334855 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Lack of battery signage.
2. Lack of stabilization in areas of access road and location.
3. Valve on tank missing plugs/caps.
4. Some fencing is on the ground.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	See stormwater		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Lack of battery signage.		
Corrective Action:	Provide proper signage	Date:	05/20/2022
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Valve on tank missing plugs/caps.		
Corrective Action:	Install cap/bull plug	Date:	04/08/2022

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Fence is not intact some is laying on the ground		

Corrective Action:		Date:	
Equipment:		corrective date	
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 211282 Type: WELL API Number: 045-07041 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced 11/2021

Corrective Action: _____

Date: _____

Facility ID: 267800 Type: WELL API Number: 045-09216 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____

Date: _____

Facility ID: 267802 Type: WELL API Number: 045-09214 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced 11/2021

Corrective Action: _____

Date: _____

Facility ID: 272467 Type: WELL API Number: 045-10086 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____

Date: _____

Facility ID: 272469 Type: WELL API Number: 045-10087 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Compaction	Fail			

Comment: 1. Lack of stabilization in areas of access road and location.Corrective Action: Install or repair required BMPsDate: 04/15/2022**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402972758	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5680971
700703948	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5680963