

MCLAUGHLIN AC 14  
INSPECTION REPORT DATED 28 FEBURARY 2022  
DOCUMENT NUMBER 701'S101786

COMMENTS FROM REPORT:

**General Comment:**

COGCC Routine Inspection Report Summary

Location is in a High Priority Habitat Area.

During this inspection the following compliance issues were observed:

☐ No evidence of tracking control BMP's.

Location shows signs of lack of stabilization BMP's in some areas (rutting is present).

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

No evidence of tracking control BMP's

Location shows signs of lack of stabilization BMP's in some areas (rutting is present)

Install or repair required BMPs per Rule 1002.f.(2)C

Corrective Action:

Date: 03/16/2022

RESPONSE:

DUE TO CURRENT CONDITIONS IN THE RANGELY AREA REQUIRED REPAIRS AND IMPROVEMENTS CAN NOT BE MADE UNTIL CONDITIONS IMPROVE. SNOW MELT AND SOFT SURFACES MAKE IT NEXT TO IMPOSSIBLE TO MOVE ANY EQUIPMENT TO MAKE IMPROVEMENTS, MOVEMENT OF SUCH EQUIPMENT WILL ONLY EXACHBERATE THE EXISTING STORMWATER PROBLEMS.

AS INDICATED ON THE ATTACHED PICTURE IMPROVEMENTS WILL BE ACCOMPLISHED:

1. RE-ESTABLISH ROAD SIDE DITCHES (RSD'S)
2. GRADE ROADS AND FILL, REMOVE ALL RUTS
3. POSSIBLE WATER BAR TO DIVERT WATER FROM ROADWAY
4. DIVERSION DITCH AS NEEDED TO CONROL THE FLOW OF WATER ONTO ROADWAY AND WELL PAD
5. ADDITIONAL BMP'S AS DETERMINED WHEN CONDITIONS ALLOW A COMPLETE REVIEW OF THE STORMWATER NEEDS.

**CHEVRON USA INC**  
**A. C. MCLAUGHLIN-62N103W 14NWNE**  
**Location # 314263**



**Access road lacks compaction/stability**



**Location lacks compaction/stability**

**CHEVRON USA INC**  
**A. C. MCLAUGHLIN-62N103W 14NWNE**  
**Location # 314263**



**Location lacks compaction/stability**



**Location lacks compaction/stability**

