

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2022

Submitted Date:

03/09/2022

Document Number:

699804237

**FIELD INSPECTION FORM**Loc ID 335287 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

19 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210773	WELL	PR	02/15/1990	GW	045-06531	GRAND VALLEY W-5-33	PR
211020	WELL	PR	01/25/1997	GW	045-06778	MOBIL MV 13-33	PR
274804	WELL	PR	05/27/2005	GW	045-13402	PA 321-33	PR
274807	WELL	PR	07/06/2005	OW	045-13399	PA 421-33	PR
274810	WELL	PR	07/06/2005	OW	045-13396	PA 521-33	PR

**General Comment:****COGCC Inspection Report Summary**

On Friday 3/4/22 at approximately 13:30 hours, I, Inspector Corey De Paolo,  
Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NENW,  
Location #335287 in Garfield County Colorado.

Refer to document #699803920 inspection conducted on 12/27/21.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Location lacks stabilization. Insufficient tracking BMP at entrance to location with a corrective action date of 3/24/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the  
Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:	MV 13-33 on free flow no tools		
Corrective Action:		Date:	

Type: Plunger Lift	# 4	
Comment:	All wells on plunger lift	
Corrective Action:		Date:
Type: Bradenhead	# 5	
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.	
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 5	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 5	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	210773	Type:	WELL	API Number:	045-06531	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	211020	Type:	WELL	API Number:	045-06778	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	274804	Type:	WELL	API Number:	045-13402	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	274807	Type:	WELL	API Number:	045-13399	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	274810	Type:	WELL	API Number:	045-13396	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail					Gravel insufficient
Other	Fail					Insufficient tracking BMP at entrance to location.
		Culverts				
Berms						
Ditches						
		Sediment Traps				
		Gravel				
		Ditches				
		Compaction				
Compaction	Fail					Location lacks stabilization.
Sediment Traps						
		Sediment Traps				
		Berms				

Comment: Location lacks stabilization. Insufficient tracking BMP at entrance to location.Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locationsDate: 03/24/2022**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<u>Refer to Storm water for corrective actions.</u>	depaoloc	03/09/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804238	Photos for Insp. #699804237	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5691054">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5691054</a>