

Inspection Photos

March 7, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335540

Location Name: Burckle A Pad

Inspection Document #: 702800015

Garfield County, CO

NWSE Section 16 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Burckle A Pad
Facility #: 335540



Photo 1. Photo taken from the north of the location facing east shows rill erosion occurring on cut slopes.



Inspection Photos
Location Name: Burckle A Pad
Facility #: 335540



Photo 2. Photo taken from the north of the location shows rill erosion occurring on cut slopes.



Inspection Photos
Location Name: Burckle A Pad
Facility #: 335540



Photo 3. Photo taken from the north of the location shows rill erosion occurring on cut slopes.



Inspection Photos
Location Name: Burckle A Pad
Facility #: 335540



Photo 4. Photo taken from the east of the location facing south shows undesirable plant species/weed debris accumulating on the location.



Inspection Photos
Location Name: Burckle A Pad
Facility #: 335540



Photo 5. Photo taken from the northern production area shows an anchor marker in disrepair.



Photo 6. Photo taken from the southeast of the location shows a support beam that is not in proper functioning condition.



Inspection Photos
Location Name: Burckle A Pad
Facility #: 335540



Photo 7. Photo taken from the tank battery shows tank “Burckle Green 02” without a bull plug.



Inspection Photos
Location Name: Burckle A Pad
Facility #: 335540



Photo 8. Photo taken at the well location shows wildlife protection control measures on well cellar are not properly installed.



Photo 9. Refer to comment under photo 8.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800015

Inspection Photos
Location Name: Burckle A Pad
Facility #: 335540



Photo 10. Photo taken from the northeast of the Location facing southeast shows interim areas covered in snow. A follow up inspection is necessary to properly assess interim reclamation.

