

Inspection Photos

March 7, 2022

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 336022

Location Name: HANGS-66S92W /9SWSW

Inspection Document #: 702800019

Garfield County, CO

SWSW Section 9 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HANGS-66S92W /9SWSW
Location ID: 336022



Photo 1. Photo taken from the south of the Location, facing west showing an overview of the Location.

Inspection Photos
Location Name: HANGS-66S92W /9SWSW
Location ID: 336022



3/7/22
+39.534566,-107.678429

Photo 2. Photo taken from the northern interim areas of the Location, facing west showing undesirable plant species/weeds (kochia). Weeds have died and will soon break off and be considered debris. Debris from undesirable plant species/weeds was observed accumulating on the Location.



Inspection Photos
Location Name: HANGS-66S92W /9SWSW
Location ID: 336022



Photo 3. Photo taken from the northeastern interim areas of the Location facing east shows debris from undesirable plant species/weeds accumulating on the Location.



Inspection Photos
Location Name: HANGS-66S92W /9SWSW
Location ID: 336022



Photo 4. Photo taken from the southern perimeter of the Location shows t-posts and fence wire being stored on Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800019

Inspection Photos
Location Name: HANGS-66S92W /9SWSW
Location ID: 336022



Photo 5. Photo taken from the southern production area of the pad shows an anchor marker in disrepair.

Inspection Photos
Location Name: HANGS-66S92W /9SWSW
Location ID: 336022



Photo 6. Photo taken from the northwestern interim areas of the Location facing east. The western portion of the project area does not appear to be progressing towards 1003 standards. Revegetation and establishment of desirable perennial grasses appears sparse.

