

Inspection Photos
Location Name: Ann 34-12
Location ID: 320040



Pic 1 Casing valve is venting gas. 2" ball valve is seized slightly open, and the ½" ball valve has a crack in the back of the valve that is venting gas. All other valves are in the close position.



Pic 2 motor house has stained soil around gas motor.

Inspection Photos
Location Name: Ann 34-12
Location ID: 320040



Pic 3 cracked ball valve. Venting gas.