

Inspection Photos
Location Name: Horth 41-15 1
Location ID: 320112



Pic 1 wellhead, All flowline valves, and master valve are in the close position. One flowline off of the top of the lubricator is seized slightly open. Flowlines downstream of valve are in the close position. Stained soil by wellhead.

Possible flowline leak by wellhead. Stained soil around flowline.

Inspection Photos
Location Name: Horth 41-15 1
Location ID: 320112



Pic 3 possible flowline leak by flowline going into ground.



Pic 4 tanks, weeds unmanaged.

Inspection Photos

Location Name: Horth 41-15 1

Location ID: 320112



Pic 5 Stained soil around water tank, spill was never cleaned up from previous inspections. Water tank, and 1 oil tank appear to have fluid in them.



Pic 6 ECD, Separator, Gas meter run, weeds unmanaged on location.