

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402984724

Date Received:

03/15/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Inspections

COGCCInspectionReports@terraep.com

Ramsey, Scott

scott.ramsey@state.co.us

Arthur, Denise

denise.arthur@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800011

Inspection Date: 03/07/2022

FIR Submit Date: 03/11/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335081

Location Name: TRANT-66S92W Number: 21SENE County: _____

Qtrqr: SENE Sec: 21 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.514440 Longitude: -107.666520

FACILITY - API Number: 05-045-00 Facility ID: 335081

Facility Name: TRANT-66S92W Number: 21SENE

Qtrqr: SENE Sec: 21 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.514440 Longitude: -107.666520

CORRECTIVE ACTIONS:

2 CA# 160123

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 01/12/2021

For new corrective actions associated with protection of slopes, install or repair required BMPs per Rule 1002.f within 48 hours (3/13/2022).

Response: CA COMPLETED

Date of Completion: 03/11/2022

Winter and mud conditions persist at this location. Location and access roads will be graded and ruts will be

Operator Comment: removed when the site dries out and conditions allow. BMPs will be cleaned out and maintained after snow cover is gone. TEP has implemented BMPs that are controlling and managing the flow of storm water (snow melt) runoff at this location and erosion is being minimized (not eliminated). The cut-slope at this location is stable, and the BMPs implemented at this location comply with Rule 1000.f.(2) and are designed to minimize (not eliminate) erosion, the transport of sediment offsite, and site degradation. See attached responses.

Also, TEP requests that the inspector please clarify where the request to repair BMPs within 48 hours comes from.

COGCC Decision: _____

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action #160123 has been addressed. See attached responses.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Env Lead

Date: 3/15/2022 10:31:35 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|-----------------------------|
| 402984738 | Vehicle tracking response |
| 402984739 | Site stabilization response |

Total Attach: 2 Files