

**Inspection Photos**  
**Location Name: Roy Annala A #2**  
**API: 05-067-08334**



**Compressor equipment has been cleaned up since last inspection.**



**Storm water in SW corner of location.**

**Inspection Photos**  
**Location Name: Roy Annala A #2**  
**API: 05-067-08334**



**Southwest corner of location where Spill/Release Point ID #481340 left the location. Storm water present during this inspection.**



**Prime mover and concrete foundation have been cleaned up since last inspection.**