

Inspection Photos
Location Name: UPRR-Sanden-EHN 1-19
Location ID: 319648



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: UPRR-Sanden-EHN 1-19
Location ID: 319648



Photo 3 location

Photo 4 TB location SW of wellsite

Inspection Photos
Location Name: UPRR-Sanden-EHN 1-19
Location ID: 319648



Photo 5 TB sign

Photo 6 TB

Inspection Photos
Location Name: UPRR-Sanden-EHN 1-19
Location ID: 319648



Photo 7 TB

Photo 8 Misc. parts, trash in out building on ES of location

Inspection Photos
Location Name: UPRR-Sanden-EHN 1-19
Location ID: 319648



Photo 9 Misc. parts, trash in out building on ES of location

Photo 10 Out building on WS of location

Inspection Photos
Location Name: UPRR-Sanden-EHN 1-19
Location ID: 319648



Photo 11 Misc. parts, trash in out building on WS of location

Photo 12 Misc. parts, trash in Out building on WS of location

Inspection Photos
Location Name: UPRR-Sanden-EHN 1-19
Location ID: 319648



Photo 13 unused Horiz. Heated Separator

Photo 14 TB location

Inspection Photos
Location Name: UPRR-Sanden-EHN 1-19
Location ID: 319648



Photo 15 TB Location



Photo 16 TB location