

Inspection Photos
Operator: Simcoe
API: 067-06845
Date: 3/14/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with grasses such as western wheatgrass, crested wheatgrass, and sand dropseed.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of area in the northern project area where stormwater flows around a cobble BMP and is eroding the fill slope.



Photo 5. View of reference area comprised pinyon and juniper woodland with gambel oak, sagebrush, mountain mahogany and Indian ricegrass in the understory.