

Inspection Photos
Operator: Simcoe
API: 067-07916
Date: 3/14/2022



Photo 1. View of project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with grasses in a dormant vegetative condition such as thickspike wheatgrass and sand dropseed.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of irrigated grass field. Grasses are in a dormant vegetative condition.