

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2022

Submitted Date:

03/16/2022

Document Number:

694500391

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ NEIDEL, KRIS _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Jackson, Spencer	972-965-5580	spencer.Jackson@scoutep.com	
Paterson, Chris	970-620-3456	chris.patterson@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
102538	PIT	AC			-	RANGLEY WEBER STATION 10	EI
463940	PIT	AC			-	Collection Station 10	EI

General Comment:

On 3/8/2021 COGCC staff, Kris Neidel inspected Collection Station 10. Weather was 32 degrees, melted snow and very muddy. Due to the mud, the focus of the inspection was related to pits, Facility 102538 and 463940 pit was observed, it appears to be in the correct location in the COGCC database. . See attached photos.

Inspected Facilities								
Facility ID:	102538	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	463940	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: EmergencyLined: YESPit ID: 463940Lat: 40.129420Long: -108.894588

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:Liner Type: Other

Liner Condition:

Comment: liner condition cannot be determined visually.

Corrective Action

Date:

Fencing:Fencing Type: Netting/Fence comFencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:Netting Type: Fence/Net ComboNetting Condition: Good

Comment:

Corrective Action

Date:

Anchor Trench Present: YESOil Accumulation: YES2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500392	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5695376