



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume		corrective date
Type: Pump Jack		# 1		
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked		# 4		
Comment:				
Corrective Action:				Date:
Type: Vertical Separator		# 1		
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run		# 1		
Comment:	<p style="color: blue;">CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR. NOTE METER WILL NEED CALIBRATED BY THE 18TH OF THIS MONTH.</p>			
Corrective Action:				Date:
Type: Bradenhead		# 1		
Comment:	<p style="color: blue;">PHOTO 4: BRHD IS NOT ACCESSABLE FROM THE SURFACE.</p>			
Corrective Action:	<p style="color: red;">Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).</p>			Date: <u>03/26/2022</u>
Type: Ancillary equipment		# 1		
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 217769 Type: WELL API Number: 071-06548 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 11/13/2011 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gradient Terraces	Pass	Culverts	Pass			
Sediment Traps	Pass	Sediment Traps	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 113644      Lat: 37.148013      Long: -104.732945

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_      Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment: NONE

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: NO      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective Action

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695105824	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5695467">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5695467</a>