

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/15/2022

Submitted Date:

03/16/2022

Document Number:

700703969**FIELD INSPECTION FORM**Loc ID 316480 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|--------------|------------------------------------|---------|
| , TEP | 970-285-9377 | COGCCInspectionReports@terraep.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 278653 | WELL | PR | 03/18/2021 | OG | 103-10611 | FEDERAL RGU 24-29-198 | PR |

General Comment:**COGCC Inspection Report Summary**

On Tuesday 3/10/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a Follow up inspection at TEP RGU 24-29, at Location # 316480 in Rio Blanco county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

C/A (Chemical containment full) from previous inspection document # 700703450 has been completed.

Location is snow covered in areas at the time of inspection. Inspector did not access location because of soft/muddy conditions and risk of further degrading pad.

During this inspection the following possible compliance issues were observed:

1. Location shows signs of lack of stabilization/ compaction and degrading.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|--|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|------------|-------|--|
| Emergency Contact Number: | | | |
| Comment: | <u>911</u> | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--------|-------|--|
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | |
|--------------------------------------------------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |

| | | | |
|------------------|-----------|--|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | | | |

| | | | |
|--------------------|--------------|-------|--|
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------------------|--------------------------------------------------------------------------------------------|-------|-----------------|
| | | | corrective date |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Dehydrator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | 1 chemical tank in plastic containment and 1 500 gallon methanol tank in metal containment | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------------------|---------|--------|
| PRODUCED WATER | 1 | 300 BBLS | HEATED STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | | | | |

| | | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--------|-------|--|
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | | |
| CONDENSATE | 1 | 300 BBLs | HEATED STEEL AST | | , | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Paint | | | | | | | |
| Condition | Adequate | | | | | | |
| Other (Content) | | | | | | | |
| Other (Capacity) | | | | | | | |
| Other (Type) | | | | | | | |
| Berms | | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | | |
| Earth | | | | | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Venting: | | | | | | | |
| Yes/No | NO | | | | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Flaring: | | | | | | | |
| Type | | | | | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 278653 | Type: | WELL | API Number: | 103-10611 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Fail | | | | | |

Comment: [1. Location shows signs of lack of stabilization/ compaction and degrading.](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 05/20/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 700703978 | Photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5695858 |