

Inspection Photos

API: 043-06219

Operator: AUSCO PETROLEUM INC

Inspection Date: 3/15/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022

Inspection Photos



Photo 1. Facing northwest along the access road. The check dams along the road have filled in with sediment and need to be maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022

Inspection Photos



Photo 2. Facing northeast toward the location. Interim reclamation has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022

Inspection Photos



Photo 3. Facing northeast at the location. The frac tank previously observed have been removed. Unused areas of the location have not been reclaimed. Previous corrective actions have not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022

Inspection Photos



Photo 4. Facing northwest at the southeast corner of the location. There is erosion occurring from the disturbed pad site which is filling in the perimeter wattles. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022

Inspection Photos



Photo 5. The wattles are degraded and are filled in with sediment. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022

Inspection Photos



Photo 6. Facing northwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022

Inspection Photos



Photo 7. There is an open trench at the location that has been excavated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022

Inspection Photos



Photo 8. The tanks at north side of the location are not properly labeled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022

Inspection Photos



Photo 9. Facing southeast at the location and toward the production equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022

Inspection Photos



Photo 10. Facing toward the topsoil pile. The topsoil piles are not stabilized and protected. Topsoil piles have not been replaced for interim reclamation. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022

Inspection Photos



Photo 11. The wattles around the topsoil are degraded and not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022

Inspection Photos



Photo 12. Facing northeast toward the location. Unused areas of the location need to be recontoured and reclaimed. Previous corrective actions have not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022

Inspection Photos



Photo 13. Drone aerial photo facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 3/15/2022