

Inspection Photos
Location Name: Gretchen Raglund 2-14
Location ID: 320322



Pic 1 flowlines from where well is located.

Pic 2 flowlines/tubing on location.

Inspection Photos
Location Name: Gretchen Raglund 2-14
Location ID: 320322



Pic 3 wellhead sign on top of tubing



Pic 4 wellhead cut off on location.

Inspection Photos
Location Name: Gretchen Raglund 2-14
Location ID: 320322



Pic 5 tanks, berms are not adequate.

Pic 6 middle tank has a leak on valve

Inspection Photos
Location Name: Gretchen Raglund 2-14
Location ID: 320322



Pic 7 valve is leaking on middle steel tank



Pic 8 separator

Inspection Photos
Location Name: Gretchen Raglund 2-14
Location ID: 320322

Mar 14, 2022 at 1:52:56 PM
39.880391,-104.293768
Adams County
COGCC



Pic 9 Separator, trash on location, weeds unmanaged.

Mar 14, 2022 at 1:53:16 PM
39.880638,-104.293643
Adams County
COGCC



Pic 10 tank does not have any signage. Berms are not adequate.

Inspection Photos
Location Name: Gretchen Raglund 2-14
Location ID: 320322

Mar 14, 2022 at 1:53:47 PM
39.880664,-104.294035
Adams County
COGCC



Pic 3 gas meter run, all have chart inside. Appear to be unused.