

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 3: WELL EQUIPMENT/ UNUSED EQUIPMENT, DRIVEHEAD AND ENGINE SKID (WELL IS TA SET UP AS MONITOR WELL.		
Corrective Action:	REMOVE UNUSED EQUIPMENT ALONG WITH THE 1" GASE SUPPLY TO ENGINE SKID, COMPLY WITH RULE 606	Date:	03/21/2022
Type	WEEDS		
Comment:	PHOTO 1: LOCATION/ VEGETATION NOT MAINTAINED AROUND WELLHEAD AND METERHOUSE.		
Corrective Action:	MAINTAIN VEGETATION, COMPLY WITH RULE606.	Date:	03/21/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	PHOTO 4: BREADENHEAD IS NOT ACCESSABLE FROM THE SURFACE.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	03/21/2022

Venting:

Yes/No	NO		
Comment:	<input type="text"/>		
Corrective Action:		Date:	

Flaring:

Type			
Comment:	<input type="text"/>		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 292460 Type: WELL API Number: 071-09401 Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: WELL HAS BEEN CONVERTED TO A MONITOR WELL.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/21/2016 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: APPROVED FORM 4 IS ON FILE DOC #400980437

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Ditches	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402981445	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5689899
695105802	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5689890