

FORM
INSPRev
X/20

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/16/2022

Submitted Date:

03/17/2022

Document Number:

701600980

FIELD INSPECTION FORM

Loc ID 337926 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 66190
Name of Operator: OMIMEX PETROLEUM INC
Address: 100 CRESCENT COURT, SUITE 700
City: DALLAS State: TX Zip: 75201

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fisher, Jeremy	970-520-8433	Jeremy_Fisher@omimexgroup.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289691	WELL	PR	05/01/2021	GW	125-10770	BLED SOE 2-2-5-45	PR

General Comment:

Routine FIR - SATISFACTORY

Location					
Lease Road:					
	Type	Access			
	comment:	Two track grassland			
Corrective Action:					Date:
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
	Type	WELLHEAD			
	Comment:	Satisfactory			
Corrective Action:					Date:
Emergency Contact Number:					
	Comment:	Satisfactory			
Corrective Action:					Date: _____
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
	Comment:	NONE			
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
	Type	PUMP JACK			
	Comment:	Steel panel			
Corrective Action:					Date:
Equipment:					
Type: Other		# 0			corrective date
	Comment:	No change in equipment inventoried. Calibration cert. in place			
Corrective Action:					Date:
Tanks and Birms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
	Comment:	PW is transported via pipeline to Mailander SWD 16B-34-6N-45W SESE 34-6N-45W			
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Birms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	

Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

Flaring:

Type				
Comment:				
Corrective Action:			Date:	

--	--	--	--

Inspected Facilities

Facility ID: 289691 Type: WELL API Number: 125-10770 Status: PR Insp. Status: PR

Producing Well

Comment: [GW](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Use BMP's for stormwater erosion management](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT