



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Ancillary equipment

# 2

Comment:

Corrective Action:

Date:

Type: Vertical Separator

# 2

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 2

Comment:

BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR. BOTH METERS WILL NEED CALIBRATED BEFORE 3-21-2022.

Corrective Action:

Date:

Type: Progressive Cavity

# 2

Comment:

Corrective Action:

Date:

Type: Bradenhead

# 2

Comment:

BOTH BRHD ARE ACCESSABLE

Corrective Action:

Date:

Type: Deadman # & Marked

# 8

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 2

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 261497 Type: WELL API Number: 071-07503 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 265217 Type: WELL API Number: 071-07758 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Sediment Traps	Pass	Check Dams	Pass			
Drains	Pass	Culverts	Pass			

Comment: [PHOTO 5: OILY WASTE IN PRIME MOVER ENGINE SKID.](#)

Corrective Action: **COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.**

Date: 03/18/2022

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: YES      Pit ID: 264477      Lat: 37.143468      Long: -104.840344

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: Adequate

Comment: \_\_\_\_\_  
 Corrective \_\_\_\_\_ Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: Adequate

Comment: \_\_\_\_\_  
 Corrective \_\_\_\_\_ Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: NONE  
 Corrective \_\_\_\_\_ Date: \_\_\_\_\_

Anchor Trench Present: YES      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: \_\_\_\_\_  
 Corrective \_\_\_\_\_ Date: \_\_\_\_\_

Permit:	Facility ID	Permit Num	Expiration Date
	264477	1120795	
	266514	200035645	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695105836	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5697707">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5697707</a>