

Inspection Photos
Operator: Simcoe
API: 067-06326
Date: 3/15/2022



Photo 1. View of the reclaimed access road from the road entrance facing northward.



Photo 2. View of the reclaimed project area from the southeastern corner facing center. Reclamation is conducted. Hay mulch and seeding rows observed. Germination and revegetation needs to be monitored during the active growing season.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of the southern project area from the southeastern corner facing westward.



Photo 5. View of reference area comprised of open sagebrush and grassland with western wheatgrass and James galleta observed.