

Inspection Photos  
Operator: Simcoe  
API: 067-09700  
Date: 3/15/2022



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing with intermediate wheatgrass, crested whatgrass, and sand dropseed.



Photo 3. View of the eastern fill slope from the southeastern corner facing northward.



Photo 4. View of erosional tunneling in the southeastern corner of the well pad, approx. 2-3 ft deep. .



Photo 5. View of reference area comprised of open grass fields and sagebrush shrubland mosaic with western wheatgrass and sand dropseed observed.