

Inspection Photos
Operator: Simcoe
API: 067-05139
Date: 3/15/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of area where the western berm has breached and is depositing large volumes of sediment on the well pad. BMPs are not maintained or adequate.



Photo 3. View of the western fill slope from the southwestern corner facing northward. Berms are not stabilized, diversion is full of sediment.



Photo 4. View of Russian thistle debris blowing off of the project area.



Photo 5. View of the northwestern diversion full of sediment and Russian thistle debris.



Photo 6. View of reference area comprised of pinyon and juniper woodland with understory of black sagebrush, yucca, James galleta.