

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2022

Submitted Date:

03/21/2022

Document Number:

699602923

**FIELD INSPECTION FORM**Loc ID 302248 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10261

Name of Operator: BAYSWATER EXPLORATION &amp; PRODUCTION LLC

Address: 730 17TH ST STE 500

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		wellinspections@bayswater.us	All Inspections
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297625	WELL	SI	01/01/2022	OW	123-28012	DYER 2-21	PA

**General Comment:**

This is a PLUGGED & ABANDONED WELL / CEMENTING inspection.  
 Well(s): 1: Plugged & Abandoned | PA.  
 Plugging Operations / Cementing. Final plugs, cement to surface.  
 Battery: Inactive | Shut-down.  
 Inactive Battery SE corner GPS coordinates: 40.522285 / -104.517823

**Location****Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:		Date:	

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 297625 Type: WELL API Number: 123-28012 Status: SI Insp. Status: PA

**Cement**Cement ContractorContractor Name: Axis Energy

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 2500'-0'Cement Volume (sx): 92 sxsGood Return During Job: YESCement Type: Class "G" Neat 15.8#Comment:

Workover Contractor: United Well Services. Rig #53.  
Cementing Contractor: Axis Energy Services.

## Reference:

Form 6N on file. Notice of Intent to Abandon date: 03/10/2022. Approved.

Form 42 on file. Notice of MIRU.

Start Date: 03/17/2022. Approved.

Form 42 on file. Notice of Plugging Operations.

Start Date: 03/17/2022. Approved.

Plugging Operations: Cement to surface.

Dyer 2-21 – CP 0, Rig up Surefire WL, set CIBP @ 2500', dump 2 sx cement on CIBP, RD WL, RIH with 31 jts of 2 3/8" tbg, EOT @ 972', Rig up Axis cementing services, mix and pump 17 bbls of class G neat cement, 90 sx, weighing 15.8#, good cement returns to surface, POOH and laydown 2 3/8" tbg, top off csg, RD cementers, ND BOP, flange up tbg head, Rig down move off.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 03/21/2022 at approximately 12:21 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: BAYSWATER EXPLORATION &amp; PRODUCTION LLC  Location Name: DYER-66N64W /2NENW  Location ID: 302248  Well Name(s):  Dyer 2-21.  API: 05-123-28012.  Location County: Weld County, Colorado  Weather: Overcast, damp from prior storm.</p> <p>While there, I observed:  Well(s): 1: Plugged &amp; Abandoned   PA.  Plugging Operations / Cementing. Final plugs, cement to surface.  Battery: Inactive   Shut-down.  Inactive Battery SE corner GPS coordinates: 40.522285 / -104.517823</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/21/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602924	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5700118">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5700118</a>