

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/14/2022

Submitted Date:

03/15/2022

Document Number:

688801100

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Hughes, Jim 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		sjninspections@ikavenergy.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481666	SPILL OR RELEASE	AC	03/07/2022		-	Thomas Jacquez A 1 Stem Valve	EI

General Comment:

On March 14, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Spill/Release Point ID #481666.

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 6

Comment: Please see Spill/Release Point ID #481666 in the COGIS database for more information regarding this event.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 04/15/2022

Reportable: YES

GPS: Lat 37.097206

Long -107.903260

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location: Comment:

COGCC Comments

Comment	User	Date
On March 14, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Spill/Release Point ID #481666. During this inspection storm water BMPs were observed downstream from the release point. Straw was observed around the release point. The operator will submit analytical results upon receipt.	hughesjo	03/15/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402985358	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5694232
688801101	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5694229