

Inspection Photos
Location Name: Hadky O Gorman #3
Location ID: 332971



Photo 1 Crew digging up casing and braden head lines to perform test



Photo 2 Casing pressure when opened

Inspection Photos
Location Name: Hadky O Gorman #3
Location ID: 332971



Photo 3 not BMP's or fencing around contaminated material

Photo 4 Contaminated material liner is ripped and into pices due to no fence or BMPs

Inspection Photos
Location Name: Hadky O Gorman #3
Location ID: 332971



Photo 5 meter calibration card

Photo 6 TNK BTRY

Inspection Photos
Location Name: Hadky O Gorman #3
Location ID: 332971



Colorado Oil and Gas Conservation Commission
40.12139, -104.78967, 1482.0m
Mar 21, 2022 11:52:41 AM



Colorado Oil and Gas Conservation Commission
40.12145, -104.78977, 1483.0m
Mar 21, 2022 11:53:00 AM

Photo 7 Open excavation

Photo 8 open excavation

Inspection Photos
Location Name: Hadky O Gorman #3
Location ID: 332971



Photo 9 open excavation

Photo 10 open excavation.

Inspection Photos
Location Name: Hadky O Gorman #3
Location ID: 332971



Photo 11 mechanical issue (sight Glass) and stained soil.

Photo 12 loc pic

Inspection Photos
Location Name: Hadky O Gorman #3
Location ID: 332971



Photo 13 loc pic

Photo 14 loc pic

Inspection Photos
Location Name: Hadky O Gorman #3
Location ID: 332971



Photo 15 loc pic



Photo 16 braden head test no gauge on braden head line.

Inspection Photos
Location Name: Hadky O Gorman #3
Location ID: 332971



Photo 17 end of test

Photo 18 end of test.

Inspection Photos
Location Name: Hadky O Gorman #3
Location ID: 332971



Photo 19 end of test.