



Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate. Sign is beginning to fade and peel, will need to be replaced in the near future.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds overgrown throughout wellsite		
Corrective Action:	Comply with Rule 606 weeds	Date:	10/27/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused pump jack disassembled on location		
Corrective Action:	Comply with Rule 606 unused equipment	Date:	10/27/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	unused pump jack has hog fence around it		
Corrective Action:		Date:	
<b>Equipment:</b>			
			corrective date
Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	disassembled and unused		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 245782 Type: WELL API Number: 123-13577 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 01/26/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday 3/22/2022 at approximately 1440 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:                      Follow up inspection to Doc # 699304327.                      George H. Gerhardt #4 at API #05-123-13577 in Weld County Colorado.                      While there, I observed a wellsite, PR at the time of inspection.                      During this inspection the following possible compliance issues were observed and are now delinquent:                      606 housekeeping: Weeds overgrown throughout location, CA date 10-27-2021.                      606 housekeeping: Unused pumpjack disassembled on location, CA date 10-27-2021.                      See attached photos.                      Location: dry, Weather: cloudy, windy and cold.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	03/22/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400102	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5701508">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5701508</a>