

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	adequate, beginning to peel and will need to be replaced in the near future		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	ancillary equip. has fabricated steel pipe and round stock		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	electric panel, meter box and transformers		
Corrective Action:			Date:
Type: Gas Meter Run	# 0		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		

Comment: gas engine		Date:
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		Date:
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		Date:
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: appears to be plumbed to surface		Date:
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:		Date:
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: See Inspection Doc # 699304490 for related shared facilities and equipment.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				Date:
Corrective Action:				Date:

Venting:

Yes/No	NO	Date:
Comment:		Date:
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 240661 Type: WELL API Number: 123-08449 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/12/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: _____

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 3/22/2022 at approximately 1405 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Follow up to inspection Doc #699304490. Glen Horton #1 at API #05-123-08449 in Weld County Colorado. While there, I observed a wellsite and tank battery, PR at the time of inspection. During this inspection the following possible compliance issues have been addressed: 430 gas measurement: Gas Meter has been removed from location. See attached photos. Location: dry, Weather: cloudy and cold. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	03/22/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400100	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5701507