

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /30SESW

Location ID:



Photo #6254 from entrance to location.

Photo #6255 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /30SESW

Location ID:



Photo #6257 flow line heating insulation open ended and not capped.



Photo #5031 from inspection #699803691 conducted on 10/7/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /30SESW

Location ID:



Photo #6256 No battery sign located at the tank battery.

Photo #5029 from inspection #699803691 conducted on 10/7/21.