

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2022

Submitted Date:

03/25/2022

Document Number:

701601079**FIELD INSPECTION FORM**Loc ID 312181 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 20275Name of Operator: CORAL PRODUCTION CORPAddress: 1600 STOUT ST STE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Nelson, Matt	303-981-3840	matt@chacoenergy.com	Inspections/Ops. Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219283	WELL	SI	10/01/2021	DSPW	075-06132	ZIEGLER A 2	SI

General Comment:[WO in process. Repairing well with liner for resolution of casing leak. Pulling tubing at time of FIR.](#)

Inspected FacilitiesFacility ID: 219283 Type: WELL API Number: 075-06132 Status: SI Insp. Status: SI**Workover**

Comment: [Rig on Site - Pulling rods and tubing, preparing well to set liner for casing leak repair.](#)
[WO in process](#)

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701601084	WO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5704295