

Inspection Photos

Location Name: Southern Ute 33-9 #20-2 Water Line

Spill/Release Point ID: 481824



Area where Spill/Release Point ID #481824 day lighted. An approximately 1' diameter hole was observed.



Proximity of release to Gaines Canyon. Pin flags on left side of photo mark release point.

Inspection Photos

Location Name: Southern Ute 33-9 #20-2 Water Line

Spill/Release Point ID: 481824



Damp area leading towards access road.



Damp and rutted area along access road.



Inspection Photos

Location Name: Southern Ute 33-9 #20-2 Water Line

Spill/Release Point ID: 481824



Damp and stained area on the opposite side of the access road.



Close up of damp erosional channel visible in top center of previous photo.

Inspection Photos

Location Name: Southern Ute 33-9 #20-2 Water Line

Spill/Release Point ID: 481824



Damp area leads towards pipeline riser.



Creek bed and bank are damp with evidence of flow.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Southern Ute 33-9 #20-2 Water Line

Spill/Release Point ID: 481824



View looking downstream in Gaines Canyon creek bed.



Photo taken looking upstream in Gaines Canyon creek bed near apparent terminus of release.