

Inspection Photos

March 24, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 311676

Location Name: DEVER-66S92W 18SWSE

Inspection Document #: 702800056

Garfield County, CO

SWSE Section 18 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DEVER-66S92W 18SWSE
Location ID: 311676



Photo 1. Photo taken from the Location entrance shows an overview of the northeastern production area.



Photo 2. Photo taken from the Location entrance shows an overview of the southwestern production area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800056

Inspection Photos
Location Name: DEVER-66S92W 18SWSE
Location ID: 311676



Photo 3. Photo taken from the well area shows unused or improperly installed well cellar grates throughout the well area.



Photo 4. Refer to Photo 3 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800056

Inspection Photos
Location Name: DEVER-66S92W 18SWSE
Location ID: 311676



Photo 5. Photo taken from the wells facing east shows subsidence in a trench.



Inspection Photos
Location Name: DEVER-66S92W 18SWSE
Location ID: 311676



Photo 6. Photo taken from well area shows BMPs to prevent wildlife access to well cellars were missing or insufficient



Inspection Photos
Location Name: DEVER-66S92W 18SWSE
Location ID: 311676



Photo 7. Photo taken from the southwest of the Location shows undesirable plant species/weed debris accumulating in interim areas and production areas adjacent to the tank battery.



Photo 8. Refer to Photo 7 comments.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800056

Inspection Photos
Location Name: DEVER-66S92W 18SWSE
Location ID: 311676



Photo 9. Photo taken from the well area shows undesirable plant species/weed debris accumulating in production areas.



Photo 10. Refer to Photo 9 comments.



Inspection Photos

Location Name: DEVER-66S92W 18SWSE

Location ID: 311676



Photo 11. Photo taken from the south of the Location facing north shows interim areas dominated by annual grass and the undesirable plant species/weed, kochia.



Photo 12. Photo taken from the south of the Location facing west. Refer to additional comments under Photo 11.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800056

Inspection Photos
Location Name: DEVER-66S92W 18SWSE
Location ID: 311676



Photo 13. Photo taken from the west of the Location facing north shows interim areas dominated by annual grass and the undesirable plant species/weeds, kochia and Russian thistle.



Photo 14. Photo taken from the west of the Location facing north shows interim areas dominated by annual grass and the undesirable plant species/weed, kochia.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800056

Inspection Photos

Location Name: DEVER-66S92W 18SWSE

Location ID: 311676



3/24/22
+39.522397,-107.708676

Photo 15. Photo taken from the north of the Location facing south shows interim areas dominated by annual grass and the undesirable plant species/weed, kochia.



3/24/22
+39.522397,-107.708676

Photo 16. Photo taken from the north of the Location shows interim areas colonized by annual grass.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800056

Inspection Photos
Location Name: DEVER-66S92W 18SWSE
Location ID: 311676



Photo 17. Photo taken from the west of the wells facing north shows rutting occurring on the pad.