

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2022

Submitted Date:

03/25/2022

Document Number:

688801116

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 Hughes, Jim _____ 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Killough, Mitch		mkillough@hilcorp.com	
Shorty, Priscilla		pshorty@hilcorp.com	All SW Inspections
Jones, Tammy		tajones@hilcorp.com	All inspections
Fischer, Alex		alex.fischer@state.co.us	
Walker, Mandi		mwalker@hilcorp.com	All Inspections SW

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481824	SPILL OR RELEASE	AC	03/25/2022		-	Southern Ute 33-9 20-2 Water Line	EI

General Comment:

On March 24, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Southern Ute 33-9 #20-2 Water Line Spill/Release Point ID #481824.

Inspected Facilities

Facility ID: 481824 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental**Spills/Releases:**Type of Spill: PRODUCED WATEREstimated Spill Volume: 13Comment: [Please refer to Spill/Release Point ID #481824 in the COGIS database for more information regarding this spill/release.](#)Corrective Action: [Control and contain spills/releases and clean up per Rule 912.a](#)Date: 04/25/2022Reportable: YESGPS: Lat 37.082680Long -107.852920

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat Long

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
<p>On March 24, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Southern Ute 33-9 #20-2 Water Line Spill/Release Point ID #481824.</p> <p>An approximate 1' diameter hole was observed during this inspection. The surrounding area was damp. Several pin flags marked Hilcorp water and gas lines. White pin flags were also observed in the area of the spill/release. The damp and stained area was followed toward the west where damp and rutted soil was observed along the access road. Damp and stained soil was observed on the other side of the road leading into an erosional channel. This damp area extended towards a pipeline riser. From the pipeline riser the damp area was observed entering the Gaines Canyon dry creek bed. Damp soil was observed traveling down the Gaines Canyon creek bed for approximately 30-40 yards.</p>	hughesjo	03/25/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801117	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5704365