

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2022

Submitted Date:

03/28/2022

Document Number:

688801120

FIELD INSPECTION FORM

 Loc ID 325276 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:

OGCC Operator Number: 55850

Name of Operator: MCLANE TRUST* DIXIE

Address: P O BOX 420

City: FARMINGTON State: NM Zip: 87499-

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Wilburn, Robert	972-907-9572	r.wilburn@tx.rr.com	SW Insp Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214448	WELL	PR	08/01/2009	GW	067-06049	SPATTER 4	EI

General Comment:

On March 24, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Dixie McLane Trust Spatter #4. For the most recent field inspection report of this facility, please refer to document #693903633.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sign near produced water AST labeled with contents, capacity, and an NFPA placard.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		37.061563,-107.870453
Comment:	Open topped steel AST with expanded metal cover.				
Corrective Action:					Date:

Paint

Condition:

Other (Content)	
Other (Capacity) 45 bbl.	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Polystar lined containment system.				
Corrective Action:				Date:

Wells Served By Facilities Above

AirsID

API Number
067-06049

API Number	AirsID
------------	--------

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 214448 Type: WELL API Number: 067-06049 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On March 24, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Dixie McLane Trust Spatter #4. For the most recent field inspection report of this facility, please refer to document #693903633. No environmental concerns were observed during this inspection.	hughesjo	03/28/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801121	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5705766