

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /2NWSE

Location ID: 334158



Photo #6288 from entrance to location.



Photo #6289 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /2NWSE

Location ID: 334158



Photo #6290 Multiple places with Debris on location.



Photo #6291 Multiple places with debris on location.


Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /2NWSE

Location ID: 334158



Network: Mar 25, 2022 at 12:31:03 PM MD
Local: Mar 25, 2022 at 12:31:03 PM MD



Network: Mar 25, 2022 at 12:31:08 PM MD
Local: Mar 25, 2022 at 12:31:08 PM MD

Photo #6292 Location lacks stabilization.

Photo #6292 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /2NWSE

Location ID: 334158



Photo #6294 Access road lacks stabilization.



Photo #6295 Sediment has been transported from access road on to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /2NWSE

Location ID: 334158



Photo #6297 Sediment has been transported on to location.




Photo #6293 Insufficient tracking controls at entrance to location.