

TEP
RMV 126-4
Location # 324075



location



location

TEP
RMV 126-4
Location # 324075



location



location

TEP
RMV 126-4
Location # 324075



Erosion



Erosion

TEP
RMV 126-4
Location # 324075



Location and Lack of stabilization/compaction



Lack of stabilization/compaction

TEP
RMV 126-4
Location # 324075



location



Lack of stabilization/compaction



TEP
RMV 126-4
Location # 324075



Lack of stabilization/compaction/erosion and sediment migration



Lack of stabilization/compaction/erosion and sediment migration



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
RMV 126-4
Location # 324075



Lack of stabilization/compaction/erosion and sediment migration



Lack of stabilization/compaction/erosion and sediment migration



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
RMV 126-4
Location # 324075



Valve missing cap/plug



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources