

Inspection Photos
Hladky-OGorman&CaryWalking1
Facility ID: 480225
Spill ID: 480738/ Remediation Project No. 19246



Photo 1 – Produced water vaults at battery. Cement vault to be removed in Rem 19246 remains in place.



Photo 2 – Open excavation for Spill 480738. Groundwater with hydrocarbon sheen visible in excavation.

Inspection Photos
Hladky-OGorman&CaryWalking1
Facility ID: 480225
Spill ID: 480738/ Remediation Project No. 19246



Photo 3 – Open excavation for Spill 480738.
Groundwater with hydrocarbon sheen visible in excavation.



Photo 4 – Open excavation for Spill 480738.
Groundwater with hydrocarbon sheen visible in excavation.

Inspection Photos
Hladky-OGorman&CaryWalking1
Facility ID: 480225
Spill ID: 480738/ Remediation Project No. 19246



Photo 5 – Soils stored on location. Lining is torn and stormwater BMPs are inadequate.



Photo 6 – Soils dug out around wellhead.