

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2022

Submitted Date:

03/28/2022

Document Number:

702400130**FIELD INSPECTION FORM**Loc ID 318436 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------------------|---------------------------------|
| , | | cogcc@kpk.com | All Inspections |
| , | | dnr_cogccenforcement@state.co.us | |
| , | | rwatzman@kpk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 241290 | WELL | PR | 01/01/2021 | OW | 123-09078 | MAHONEY 2 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | |
| Corrective Action: | Date: _____ |

| | | |
|---------------------------|---------------------------------------|------------------|
| Good Housekeeping: | | |
| Type | WEEDS | |
| Comment: | Dead weeds around ancillary equipment | |
| Corrective Action: | Comply with Rule 606 | Date: 02/07/2022 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | |
|--------------------|--|-------|
| Fencing/: | | |
| Type | PUMP JACK | |
| Comment: | hog fence | |
| Corrective Action: | | Date: |
| Type | OTHER | |
| Comment: | ancillary equip. has fabricated steel pipe | |
| Corrective Action: | | Date: |

| | | | |
|---------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 1 | | |
| Comment: | electric panel, meter box and transformers | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | appears plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | electric motor | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

Inspected FacilitiesFacility ID: 241290 Type: WELL API Number: 123-09078 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 01/26/2022Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Monday 3/28/2022 at approximately 1450 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p>Location: Mahoney 2</p> <p>API #05-123-09078</p> <p>County: Weld.</p> <p>While there, I observed a wellsite, PR at the time of inspection.</p> <p>During this inspection the following possible compliance issue was observed and is now delinquent:</p> <p>606 houskeeping: Dead Weeds around ancillary equip. CA Date 2-7-2022.</p> <p>During this inspection the following possible compliance issues have been cleared:</p> <p>419.a.(1),(2) Bradenhead access: Bradenhead is accessible initial inspection the access was covered with dirt and not visible.</p> <p>419.b.(5) Bradenhead Monthly Reporting: bradenhead appears to be plumbed to surface for testing.</p> <p>Location: Dry, Weather: cloudy.</p> <p>A follow up on this site inspection needs to be conducted.</p> <p>Compliance issues appear to have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | revasr | 03/28/2022 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 702400131 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5706220 |