

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/22/2022

Submitted Date:

03/22/2022

Document Number:

702400095

FIELD INSPECTION FORM

Loc ID 318399 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		dnr_cogccenforcement@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241226	WELL	TA	12/30/2019	OW	123-09014	1415 CORP UNIT F 1	TA

General Comment:

[Edited comment language requiring MIT.- cpesicka, 03/24/2022](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:		Date:	<input style="width: 100%;" type="text"/>

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	concrete slab for pump jack, unused ancillary equipment.		
Corrective Action:	Comply with Rule 606, Statewide unnecessary equipment, weeds, waste, and trash requirements.		Date: 10/28/2021

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	unused ancillary equipment has fabricated steel pipe and round stock		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Ancillary equipment	# 1			
Comment:	unused Electric panel, meter box and transformers			
Corrective Action:		Date:		
Type: Bradenhead	# 1			
Comment:	appears to be plumbed to surface			
Corrective Action:		Date:		

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	See Inspection Doc # 699304331 for information concerning well shared facilities and equipment				
Corrective Action:		Date:			

Paint	
Condition	<input style="width: 100%;" type="text"/>
Other (Content)	<input style="width: 100%;" type="text"/>

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date: <input style="width:100px;" type="text"/>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: <input style="width:100px;" type="text"/>

Flaring:

Type		
Comment:		
Corrective Action:		Date: <input style="width:100px;" type="text"/>

Inspected Facilities

Facility ID: 241226 Type: WELL API Number: 123-09014 Status: TA Insp. Status: TA

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: SUSX

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 12/23/2019

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: [TA, Form 04 TA Doc #401784269 5-16-2019. Well last produced March 2005. This well does have a MIT 12/12/2019.](#)

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/25/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 3/22/2022 at approximately 1250 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up inspection to Doc # 699304333 Operator: KP Kauffman Location: 1415 Corp. Unit F #1 API #05-123-09014 County: Weld. While there, I observed a wellsite, TA at the time of inspection. During this inspection the following possible compliance issue has been addressed: 606 housekeeping: weeds growing around WH and location have been cut. During this inspection the following possible compliance issues are now delinquent: 606 housekeeping: Unused concrete slab where pump jack would be placed, unused transformers and meter box, CA date 10-28-2021. See attached photos. Location: dry, Weather: cloudy, windy and cold. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	03/22/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402992494	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5701512
702400096	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5701505