

Inspection Photos
Location Name: Florida River Estates 33-9 #17-3A
API: 05-067-09367



#17-3A well head and surrounding area are stained. Damp soil observed during this inspection.

Stained and wet area around #17-3 well head.

Inspection Photos
Location Name: Florida River Estates 33-9 #17-3A
API: 05-067-09367



Standing water beneath #17-3 well head.



Production equipment on location.

Inspection Photos
Location Name: Florida River Estates 33-9 #17-3A
API: 05-067-09367



Illegible labels on northern AST.



Illegible labels on southern AST.