

Inspection Photos

03/28/2022

Operator: NONSUCH NATURAL GAS INC #
10163

Location ID: 324169
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC # 10163
Location ID: 324169



Photo 1: Photo shows wildlife protection devices to prevent wildlife access remain missing or insufficient from the secondary containment BMPs at the tanks.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC # 10163
Location ID: 324169



March 28, 2022
39.1965162N 108.2688086W



March 28, 2022
39.51410739N 108.19964657W

Photo 2: Photos taken from the interim areas on the North/East ends of the Location. Unable to find evidence that additional reclamation performed; reclamation not progressing towards 1003 standards. Photo also shows control measures to protect/stabilize the slopes of the Location remain missing or insufficient. Soils are loose, and composed of fine and rocky materials.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



March 28, 2022
39.51374876N 108.2001048W



March 28, 2022
39.51409047N 108.20024531W

Photo 3: Photos taken from the interim areas on the west end of the Location. Unable to find evidence that additional reclamation performed; reclamation not progressing towards 1003 standards. Photo also shows control measures to protect/stabilize the slopes of the Location, and to prevent offsite sediment transport remains missing or insufficient. Soils are loose, and composed of fine and rocky materials.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 4: Photos taken from the slopes on the North/East end of the Location. Photo shows erosion and sediment transport.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC # 10163
Location ID: 324169



Photo 5: Photo taken from the access road on the north end of the Location. Photo shows erosion degradation has persisted along access road; control measures to stabilize, manage runoff and minimize erosion and sediment transport remains missing or insufficient at access road. 2 foot measuring stick for reference (arrow).

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 6: Photo taken from the access road on the north end of the Location. Photo shows erosion degradation has persisted along access road; control measures to stabilize, manage runoff and minimize erosion and sediment transport remains missing or insufficient at access road. 2 foot measuring stick for reference (arrow).

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 7: Photo taken from the access road on the north end of the Location. Photo shows erosion degradation has persisted along access road; control measures to stabilize, manage runoff and minimize erosion and sediment transport remains missing or insufficient at access road. 2 foot measuring stick for reference (arrow).

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC # 10163
Location ID: 324169



Photo 8: Photo shows sediment deposition due to erosion degradation and sediment transport from the access road.