

Inspection Photos

API: 071-06811

Operator: WAPITI OPERATING LLC

Inspection Date: 3/29/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06811 | Date: 3/29/2022

Inspection Photos



Photo 1. The disturbed bare soils along the roadside at the creek crossing have not been seeded and stabilized. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06811 | Date: 3/29/2022

Inspection Photos



Photo 2. The disturbed bare soils along the roadside at the creek crossing have not been seeded and stabilized. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06811 | Date: 3/29/2022

Inspection Photos



Photo 3. Facing at south side of the road at the additional culvert inlet. Disturbed bare soils have not been seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06811 | Date: 3/29/2022

Inspection Photos



Photo 4. Facing at south side of the road at the additional culvert inlet. Disturbed bare soils have not been seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06811 | Date: 3/29/2022

Inspection Photos



Photo 5. Facing northeast along the road. Areas of erosion along the road side have been filled in and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06811 | Date: 3/29/2022

Inspection Photos



Photo 6. Facing northwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06811 | Date: 3/29/2022